

VEHICLE INSPECTION REPORT

BF23YOC

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/06/2023

Colour WHITE

Gearbox MANUAL

Year 2023

VIN ZCFAH1EF002729385

Axle Combi 4x2

Mileage 68,190 Km Warranted

Body Style Pole Erection Unit

Rear Suspension Steel

Fuel Type Diesel

Service history Yes

GVW 12000kg

Service documents Printout

PALFINGER PK 9.501 REMOTE CRANE (YEAR 2022), AUTOGUIDE 40PXV AUGER (YEAR 2022), POLE JACK, HEATED DRYING LOCKER, 240V POWER, AUGER EXTENSION POLE, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Air conditioning
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm




2: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



3: Door osf
Dented
Over 30mm

4: Qtr Panel osr
Rusted
Over 5mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Door nsf
Dented
Over 30mm



7: Wing nsf
Chipped
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	