

VEHICLE INSPECTION REPORT



Land Rover Defender 110 2.2 TDCI

Inspection	Vehicle	Vehicle		
Serious Damage? No	VAT	Plus VAT		
	V5	Buyer To Apply		

Deta	ils
------	-----

Reg. date	23/04/2013	Colour	WHITE	Gearbox	MANUAL
Year	2013	VIN	SALLDHWP7DA430421	Gears	6
Mileage	109,312 Miles	Body Style	Access Platform	Axle Combi	4x4
	Warranted	MOT Due	30/07/2025		
Fuel Type	Diesel				

HYDRAULIC PIPE ISSUE WINCH, NIFTY V130T LIFT, TOW BAR

Tyres	
Tyres NSF	
NSR	
OSF	
OSR	
OSR Spare	

Features

Park assist camera

• Front electric windows

Central locking

Photos





































Condition Check



Damage Photos





2: Bonnet Dented Over 30mm



3: Bonnet Scratched Over 25mm Thru Paint



5: Wing nsf Dented Over 30mm



7: Door nsf Dented Over 30mm



4: Panel Front Dented Over 30mm



6: Wing nsf Dented Over 30mm



8: Door nsf Dented Over 30% Of Panel



9: Sill ns Dented With Paint Damage



11: Qtr Panel osr Scratched Over 25mm Thru Paint



10: Qtr Panel nsr Scratched Over 25mm Thru Paint



12: Door osf Dented Over 30mm



13: Door osf Dented Over 30mm



14: Sill os Dented With Paint Damage



15: Wing osf Dented Over 30mm



16: Wing osf Dented Over 30mm



17: Carpets Front Missing Replace



18: Door Pad osf Soiled Heavy



19: Seat Base Cover osf Torn Over 3mm

Interior



20: Seat Base Cover nsf Torn Over 3mm

Carpet Condition Seat Condition	Poor Poor		Upholstery Condition Odour	Poor -	
Engine Runs		OK	No Excessive Smoking		ОК
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			